








Vehicle: (make & model)	Mercedes E200 2015 Model	Registration no: DBS-59V
Name:	SR Auto Traders	Phone: 94172922
Address:	Inspected at 92a Reserve Road Artarmon	
Compliance plate/serial no:	WDD2073342F324613	Odometer: 88567
Report no:	004613	Date: 7.5.24

Pass = satisfactory/consistent with mileage**Fail = needs service/repairs**

Engine <input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail	There are no visible oil leaks. Fluid levels are all normal. No abnormal engine noise or excessive fumes/smoke detected. A head gasket pressure test was performed with a pass reading. There is no sign of head gasket leakage. The engine functioned with no faults or signs of excessive engine wear. The manufacturers servicing schedule should be considered when buying a used car.
Cooling system <input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail	Checks for coolant leaks undertaken with no leaks detected. The coolant levels were all normal. No faults evident in the hoses. The cooling system functioned with no sign of engine overheating. The cooling fan operation was normal. Condition of the radiator and hoses showed wear consistent with kilometres. The cooling system functioned with no faults evident at the time of inspection.
Ignition <input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail	Petrol ignition system functioned with no faults evident.
Fuel system <input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail	There were no fuel leaks detected. The fuel pump and injectors functioned with no faults evident. The entire fuel system functioned normally with no faults evident.
Tyres, wheels & brakes <input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail	The braking system functioned with no faults. There was no signs of any brake fluid leaks in the hydraulic system. The front/rear brake pads and disc rotors are all satisfactory (always check at the next service). The tyres are all good (better than 70%). The condition of the alloy wheels are also good with no obvious scratches or gutter rash.
Underbody, steering & suspension <input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail	Normal wear was evident in steering & suspension components typical for kilometers traveled (no repairs required). No faults evident in the under-body. Condition of the exhaust system shows wear consistent with age & kilometers (no exhaust leaks detected). There were no faults evident in the steering system or the suspension. Continued servicing & maintenance must be expected as the vehicle ages.
Transmission /drive train <input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail	Auto transmission. There were no signs of transmission oil leaks. The transmission functioned as it should. The vehicle has normal wear in the drive shafts and cv joints consistent with the kilometers traveled (no repairs required at time of inspection). There were no faults evident in the transmission, drive shafts or the cv joints.
Electrical <input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail	A battery load test returned a pass reading. Condition of the battery terminals was good. The headlights and indicators functioned with no faults. An alternator voltage charge test was returned a reading of 14.00 (normal range). The wiring and connections are as per the manufacturers specs with no faults evident. The engine management system functioned with no faults detected.

Interior <input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail	Minor wear was evident in carpets, seats and interior trim. The interior of the vehicle is in very good condition for its age. All electric components appear to be in good working order. There are no faults evident in the interior and its components.
Exterior <input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail	Very minor surface scratches and stone chips are evident in various areas (most will remove when the vehicle gets detailed). The vehicle show no signs of major paint/panel repairs. The condition of the paintwork & body panels is very good for its age & the kilometers.
Road test <input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail	No faults evident in the engines performance. The transmission shifted smoothly & functioned normally. The braking/ABS system functioned with no faults. The steering and suspension functioned with no faults. The road test was good and produced no faults. It drove well & the overall performance was considered to be good for the age and kilometers traveled.



Overall IVI vehicle condition

		✓	
Unsatisfactory	Satisfactory	Good	Excellent

General comments	This E200 is in very good condition for its age & the kilometers. It drove well, has a good service history (service due - Dealer should complete) and has been well maintained. A regular service schedule along the lines of manufacturers recommendations should be continued for optimum performance and reliability. VEHICLE CONDITION RATING (very good for its age & kilometers). Inspected by Brian Cox. Vehicle Inspector Licence 44249 (MVRIA) MTA AUTHORISED
-------------------------	---

IMPORTANT INFORMATION ABOUT THIS INDEPENDENT VEHICLE INSPECTIONS REPORT

This IVI report is a general inspection of the vehicle. It takes into account only the matters listed on the report. This report does not in any way affect normal warranty obligations. The report lists the defects that were visible at the time of the inspection. In preparing the report, we conducted a visual inspection and road test. We did not undertake any investigations which require the removal or dismantling of any part of the vehicle including the engine, wheels or brakes. We cannot inform you of the existence of a defect if we cannot see it or it does not appear during the road test and/or inspection. This report is not a warranty or guarantee. It is a guide to the condition of the vehicle and the decision whether to obtain the vehicle rests entirely with the purchaser. Independent Vehicle Inspections excludes all warranties and conditions that may be implied by law.

- What we check:** (Independent Vehicle Inspections visually check all the items listed on this report)
- Engine condition
 - Cooling system
 - Fuel system
 - Ignition system
 - Tyres, wheels and brakes
 - Underbody
 - Electrical
 - Interior/Exterior
 - Road test
- What we don't check:**
- Oil and fuel consumption
 - Source of a leak if the area is dirty
 - Oil pump strainer for any build-up of sludge
 - Engine cylinder compression
 - Operation of cassette, CD or DVD player
 - Sound or radio reception
 - Navigation systems
 - Alarm systems
 - Bodywork water leaks, or their source
 - Airbag functionality

Camshaft drive and belt:
 As a drive belt cannot be inspected, we suggest that you check the service records for this vehicle to ensure that it has been changed in accordance with manufacturer's recommendations.

Paint and/or panel repairs:
 Repairs and replacement panels deemed by Independent Vehicle Inspections at the time of inspection to be in a satisfactory condition will not be recorded.

Paint chips/Windscreen chips/Scratches:
 Chips in the paint or windscreen or scratches to the vehicle's paint will only be recorded if they are regarded as either irregular or excessive.

This report is not a warranty or guarantee for any purpose and is only valid at the inspection date.

To the extent permitted by law, Independent Vehicle Inspections exclude all warranties and conditions that may be implied by law.